



The 2013 Street Program recommendations for the different streets to be rehabilitated with the MFT Funds through the IDOT Bureau of Local Roads and Village General Funds:

BASE BID Recommendations

Rehabilitation of Old Hicks Road

- a. Remove existing 2" of surface hot-mix asphalt (HMA). Place 2" of HMA surface course.
- b. Place 3/4" HMA leveling binder to fill roadway voids and correct roadway grades.
- c. Perform full depth Class D patching in areas where pavement is failing. Approximately 10% of total pavement area was assumed failing for calculating patching quantities.
- d. Restripe roadway, crosswalks, and stop bars.
- e. Regrade roadside ditches to allow positive drainage and keep water off of pavement.
- f. Restore landscaping in regarded ditches.
- g. Miscellaneous surface and full depth pavement patching on the following Village Roadways:

- Indian Creek Road
- Checker Road
- Holly Lane
- North Krueger Road
- Cuba Road
- Mardan area

Total Construction and Engineering Costs (Design and Construction) for Patching and Other 2013 Street Program Improvements are Not to Exceed.